


Index No. G 11

CASS COUNTY LAND CORNER RECORD

T. 144 R. 25 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C 1/4 Corner common to sections 9



EXISTING SURVEYS

Original Government Survey  
Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species \_\_\_\_\_  
Diameter NOT SET IN ORIGINAL SURVEY  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1985 By USFS  
Location filed Corner Certificate - Doc # 385578  
Monument Set 2 1/2 x 60" pipe w/ brass cap.

Evidence of Subsequent Corner Restoration  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects			
Species	<u>Jack Pine</u>	<u>Jack Pine</u>	<u>N. Pine</u>
Diameter	<u>12.9"</u>	<u>16.2"</u>	<u>15.9"</u>
Bearing	<u>N34E</u>	<u>S41W</u>	<u>N43W</u>
Distance	<u>16.37'</u>	<u>31.41'</u>	<u>47.73'</u>

Bearing Trees, Reference Objects  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Ken Whitehorn - USFS - 1985

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_