


Index No. G13

CASS COUNTY LAND CORNER RECORD

T. 144 R. 25 M. 5TH Coordinates: X _____ Y _____
E14 9 Corner common to sections 9,10



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1876
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species NO trees
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Jim Parker - 1985
Set lost - 5/8" x 11' aluminum rod w/cap
Steel sign post south 4.0
Doc. # 281675

Re monumentation certificate prepared _____ By _____
Filed at _____ Date _____