Index No. G5

CASS COUNTY LAND CORNER RECORD

T. 144 R. 25 M. 5TH Coordinates: X _____ Y _____

E1/4 7 Corner common to sections 7, 8



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1876

Original monument Post

Bearing Trees

Species	Cedar	Tam		
Diameter	6"	12"		
Bearing	N16W	N71E		
Distance	23 LKS	46 LKS		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Jim Parker - 1985
set lost 5/8" x 5' aluminum rod w/cap
12" Cedar N 50°E 13.48'
13" Cedar N 57°W 22.98'
Doc. # 281673

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____