

Distance  
Bearing  
Diameter  
Species

Bearing Trees, Reference Objects

Monument  
Location filed  
Year surveyed

By

Subsequent Corner Restoration

Distance  
Bearing  
Diameter  
Species

Bearing Trees

Year surveyed 1876  
Original monument Post

Original Government Survey

EXISTING SURVEYS

Original Evidence Found

Year of search By

Monument found

Original Bearing Trees Found

Distance  
Bearing  
Diameter  
Species

Evidence of Subsequent Corner Restoration


Year of search By

Bearing Trees, Reference Objects

Index No. 513

CASS COUNTY LAND CORNER RECORD

T. 144 R. 25 M. 574 Coordinates: X 9/10/15/16  
Corner common to sections N E 16



Evidence of Subsequent Corner Restoration Found

Year of search By

Certificate - Jim Parker - 1985  
 Set obliterated - 5/8" x 5' aluminum rod w/cap  
 6" Cedar - N5°E 8.48'  
 8" Cedar S52°E 6.70'  
 4" Tam S35°W 2.49'  
 5" Cedar N47°W 5.89'  
 Doc. # 281709

Subsequent Corner Restoration

Year surveyed By

Location filed

Monument

Remonumentation certificate prepared

By

Filed at

Date