

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Monument

Location filed

Year surveyed By

Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Bearing Trees

Year surveyed 1876
Original monument lost

Original Government Survey

EXISTING SURVEYS

T 144 R 25 M 5TH Coordinates: X Corner common to sections 14/15

CASS COUNTY LAND CORNER RECORD

Index No. 117

Subsequent Corner Restoration

Year surveyed By
Location filed
Monument

Evidence of Subsequent Corner Restoration Found

Year of search By

Certificate - Jim Parker - 1985
Set obliterated from 1900 Corps m fo - set
5/8" x 8' aluminum rod w/cap
6" Spruce S35E 5.30'
5" Spruce N85W 6.87'
Doc # 281718

Remonumentation certificate prepared

By

Filed at

Date

Evidence of Subsequent Corner Restoration


Species
Diameter
Bearing
Distance

Original Bearing Trees Found

Year of search By
Monument found

Original Evidence Found

O = Corner



Bearing Trees, Reference Objects

Year of search By