

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Monument

Location filed

Year surveyed By

Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Bearing Trees

Original Government Survey

Year surveyed 1876
Original monument lost

EXISTING SURVEYS

Coordinates: X 144 R 25 M 574
Corner common to sections 16/21

CASS COUNTY LAND CORNER RECORD

Index No. N 11

Bearing Trees, Reference Objects

Year of search By

Evidence of Subsequent Corner Restoration


Species
Diameter
Bearing
Distance

Original Bearing Trees Found

Year of search By
Monument found

Original Evidence Found

O = Corner



Subsequent Corner Restoration

Year surveyed By
Location filed
Monument

Evidence of Subsequent Corner Restoration Found

Year of search By

Certificate - Jim Parker - 1985
Set lost 2 1/2" l.p. w/ brass cap
9" Ash 523°E 3.77'
9" Birch N86°W 3.81'
Doc. # 281806

Remuneration certificate prepared By

Filed at Date