

Species  
Diameter  
Bearing  
Distance

Bearing Trees, Reference Objects

Monument  
Location filed  
Year surveyed

By

Subsequent Corner Restoration

Species  
Diameter  
Bearing  
Distance

No Bearing Trees

Year surveyed 1876  
Original monument lost

Original Government Survey

EXISTING SURVEYS

Original Evidence Found  
Year of search  
Monument found

Original Bearing Trees Found

Species  
Diameter  
Bearing  
Distance

Evidence of Subsequent Corner Restoration


Year of search  
By

Bearing Trees, Reference Objects

Index No. N 23

CASS COUNTY LAND CORNER RECORD

Coordinates: X 1324  
M. 5TH  
N 144 R 25  
N 144 R 24  
Corner common to sections 1324



Evidence of Subsequent Corner Restoration Found

Year of search By

Certificate - Jim Parker - 1985  
Set lost - 5/8" x 13' aluminum rod w/cap  
Steel sign post 3.60' East  
Doc. # 281947

Subsequent Corner Restoration

Year surveyed By

Location filed  
Monument

Remonumentation certificate prepared

By

Filed at

Date