

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Monument

Location filed

Year surveyed By

Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Bearing Trees

Original monument lost

Year surveyed 1876

Original Government Survey

EXISTING SURVEYS

T. 144 R. 25 M. 57H Coordinates: X E 77 21 Corner common to sections 21, 22 Y

CASS COUNTY LAND CORNER RECORD

Index No. 013

Subsequent Corner Restoration

Year surveyed By

Location filed

Monument

Evidence of Subsequent Corner Restoration Found

Year of search By

Certificate - Jim Parker - 1985
Set lost 2 1/2" I.P.W / brass cap.
4" Spruce 575 E 4.60'
6" Spruce N 12 W 16.73'
Doc. # 281951

Remonumentation certificate prepared

By

Filed at

Date

Bearing Trees, Reference Objects

Evidence of Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Original Bearing Trees Found

Monument found

Year of search By

Original Evidence Found

O = Corner

