

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Monument

Location filed

Year surveyed By

Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Cedar 14" 9" Cedar
Bearing Trees
8.75 N24W 57BE 11.75
8.75

Original monument lost

Year surveyed 1876

Original Government Survey

EXISTING SURVEYS

Original Evidence Found

Year of search By

Monument found

Original Bearing Trees Found

Species
Diameter
Bearing
Distance

Evidence of Subsequent Corner Restoration

Year of search By


Bearing Trees, Reference Objects

Index No. 85

CASS COUNTY LAND CORNER RECORD

T. 144 R. 25 M. 5TH Coordinates: X 1920

Corner common to sections 19, 20



Evidence of Subsequent Corner Restoration Found

Year of search By

Certificate - Jim Parker - 1985
Set lost - 2 1/2" I.P. w/ marked brass cap.
5" Ash N30E 12.85'
5" Ash N20W 15.37'
Doc. # 281949

Subsequent Corner Restoration

Year surveyed By

Location filed

Monument

Remonumentation certificate prepared

By

Filed at

Date