

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Monument _____

Year surveyed _____
 Location filed _____

By _____

Subsequent Corner Restoration

Species Birch 14"
 Diameter 13 LKS
 Bearing N71W
 Distance 578E
13 LKS

Bearing Trees Sugar
6"

Year surveyed 1876
 Original monument lost

Original Government Survey

EXISTING SURVEYS

Index No. 09
 144 P. 25 M. 5TH Coordinates: X E114.30
 Corner common to sections 20, 21

CASS COUNTY LAND CORNER RECORD

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Jim Parker - 1985
Srt lost - 2 1/2" I.P. w/ stamped brass cap
11" Basswood 520°E 16.63'
8" Maple 575°W 18.70'
Doc. # 281950

Bearing Trees, Reference Objects

Monument _____

Year surveyed _____
 Location filed _____

By _____

Subsequent Corner Restoration

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees _____

Year surveyed _____
 Original monument _____

Original Government Survey

Original Evidence Found _____
 Year of search _____
 Monument found _____

Original Bearing Trees Found _____


Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration

By _____

Year surveyed _____
 Location filed _____

Bearing Trees, Reference Objects



Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____