

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Monument _____

Location filed _____

Year surveyed _____ By _____

Year of search _____ By _____

Evidence of Subsequent Corner Restoration

Subsequent Corner Restoration

Species Willow 6"
Diameter 4"
Bearing N 80° E
Distance 140 LKS

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Year surveyed 1876
Original monument lost

Original Government Survey

Year of search _____ By _____
Monument found _____

Original Evidence Found

EXISTING SURVEYS

T 144 R 25 M 5TH Coordinates: X 22,27 Y _____
Corner common to sections 22,27

CASS COUNTY LAND CORNER RECORD

Index No. R 15

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed _____

Monument _____

Certificate - Jim Parker - 1985
set lost - 2' 2" 1" P. w/cap.
9" Basswood N 70° W 26.80'
9" Basswood S 57° W 42.10'
DOC. # 281961

Remuneration certificate prepared _____

By _____

Filed at _____

Date _____

