

T. 144 R. 25 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 29 Corner common to sections 20, 21, 28, 29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1876  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Lynn</u>	<u>Sugar</u>	<u>Sugar</u>	<u>Sugar</u>
Diameter	<u>18"</u>	<u>6"</u>	<u>8"</u>	<u>8"</u>
Bearing	<u>N 15° E</u>	<u>S 74° W</u>	<u>S 60° E</u>	<u>N 13° E</u>
Distance	<u>57 links</u>	<u>19 links</u>	<u>42 links</u>	<u>69 links</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 10/1984 By J.H. Parker, LS 9235  
Location filed: Certificate of Location T144N R25W  
Monument: Set 2.5" by 24" iron pipe w/ brass cap S20 | S21  
at the obliterated position at intersection of S29 | S28  
Township Rds. to S. and W. 1985  
RLS 9235

Evidence of Subsequent Corner Restoration

Year of search 11/2017 By CCHD/SO  
Location filed: #2017.017  
Monument: Found 20d nail  
at intersection of witnesses, near PI of Twp Rds, USFS brass  
cap, horizontal, 2.5' W.

Bearing Trees, Reference Objects

Species	<u>Oak</u>	<u>Aspen</u>	<u>Elm</u>	_____
Diameter	<u>6"</u>	<u>6"</u>	<u>6"</u>	_____
Bearing	<u>N 68° W</u>	<u>S 20° E</u>	<u>S 84° W</u>	_____
Distance	<u>77.91'</u>	<u>57.09'</u>	<u>173.69'</u>	_____

Bearing Trees, Reference Objects

Species	<u>Burr Oak</u>	<u>Aspen</u>	<u>P. Pole</u>	<u>Tele. Ped.</u>
Diameter	<u>6"(1984)</u>	<u>12"(1984)</u>	_____	<u>Post</u>
Bearing	<u>N 68° E</u>	<u>S 20° E</u>	<u>N 77° W</u>	<u>N 16° E</u>
Distance	<u>77.91'</u>	<u>56.92'</u>	<u>84.64'</u>	<u>37.85'</u>

Subsequent Corner Restoration

Year surveyed 7/2019 By CCHD/SO  
Location filed: #2017.017  
Monument: Reset USFS brass cap  
down 0.5', near centerline PI of 80th Avenue and 128th Street,  
witnesses are all good.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_

Species  
Diameter  
Bearing  
Distance

Bearing Trees, Reference Objects

Monument  
Location filed  
Year surveyed

By

Subsequent Corner Restoration

Species  
Diameter  
Bearing  
Distance

Bearing Trees

Species  
Diameter  
Bearing  
Distance

Species  
Diameter  
Bearing  
Distance

Original Bearing Trees Found

Year of search

By

Original Evidence Found

EXISTING SURVEYS


Original Government Survey

Year surveyed 1876  
Original monument lost

T. 144 R. 25 M. 577 Coordinates: X 20,21,28,29  
Y NE 29 Corner common to sections

CASS COUNTY LAND CORNER RECORD

Index No. R9



Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Jim Parker - 1985  
Set lost - 2 1/2 x 24" I.P. w/cap.  
6" oak N68E 77.91'  
6" Aspen S20E 57.09'  
6" Elm S84W 173.69'  
Doc. # 281958

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_

R-9