


T. 144 R. 25 M. 5th Coordinates: X _____ Y _____
C 1/4 Corner common to sections 28



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

NOT SET IN ORIGINAL SURVEY

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 5/1985 By K.L. Whitehorn, LS 14677
Location filed: Certificate of Location T144N R25W
Monument: Set 2.5" by 54" iron pipe w/ brass cap C 1/4 S28
up 24", at intersection of 1/4 lines as provided 1985
by J.H. Parker, LS 9235 and witnessed. RLS 14677
Steel Sign Post, North, 3.0'
Steel Sign Post, East, 3.0'

Bearing Trees, Reference Objects

| Species | Aspen | Red Maple | Aspen |
|----------|---------|-----------|---------|
| Diameter | 7.5" | 11.3' | 5.8" |
| Bearing | N 39° E | S 69° W | N 23° W |
| Distance | 72.66' | 17.56' | 49.61' |

Evidence of Subsequent Corner Restoration

Year of search 10/2017 By CCHD/SO
Location filed: #2017.017
Monument: Found USFS brass cap up 2.3', at corner of field, 40'+/- S. of woods line. This survey determined this monument is N 18°20'44" W, 0.71' from true intersection. All 1985 witnesses fit the monument.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. T 11

CASS COUNTY LAND CORNER RECORD

T. 144 R. 25 M. 5th Coordinates: X _____ Y _____
C 114 Corner common to sections 28



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Bearing Trees

Species _____
Diameter NOT SET IN ORIGINAL SURVEY
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1985 By USFS
Location filed Corner Certificate - Doc # 285586
Monument Set 2 1/2 x 54" i.p. w/ brass cap

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|--------------------|----------------|------------------|---------------|
| <u>Aspen</u> | <u>7.5"</u> | <u>N39E</u> | <u>22.66'</u> |
| <u>Red Maple</u> | <u>11.3"</u> | <u>S69W</u> | <u>17.56'</u> |
| <u>Aspen</u> | <u>5.8"</u> | <u>N23W</u> | <u>49.61'</u> |
| <u>Metal Posts</u> | <u>8' long</u> | <u>N & E</u> | <u>3'</u> |

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

T-11

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Ken Whitcomb - USFS - 1985

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____