


T. 144 R. 25 M. 5th Coordinates: X _____ Y _____
E 1/4 28 Corner common to sections 27, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1876
Original monument Post

Original Evidence Found

Year of search 1908 by Flynn
Monument found _____
Surv Rec. #416, Book C, pg. 183

Bearing Trees

Species	<u>Aspen</u>	<u>White Pine</u>	_____
Diameter	<u>6"</u>	<u>7"</u>	_____
Bearing	<u>N 30° E</u>	<u>N 75° W</u>	_____
Distance	<u>20 links</u>	<u>11 links</u>	_____

Original Bearing Trees Found

Species	<u>White Pine</u>	_____	_____
Diameter	<u>7"</u>	_____	_____
Bearing	<u>N 75° W</u>	_____	_____
Distance	<u>11 links</u>	_____	_____

Subsequent Corner Restoration

Year surveyed 7/1908 By J.H. Flynn, Co. Surveyor
Location filed: Survey Record #416, Book C, page 183
Monument: Found corner and original witness, new witnesses as follows.

Evidence of Subsequent Corner Restoration

Year of search 10/1984 By J.H. Parker, LS 9235
Location filed: Certificate of Location T144N R25W
Monument: Set 2.5" by 5' iron pipe w/ brass cap at obliterated position, on N-S fence line and prorata distance between Sec. corners, 7'+/- N. on fence corner. 1/4 S28 | S27 1984 RLS 9235

Bearing Trees, Reference Objects

Species	<u>White Pine</u>	<u>White Pine</u>	_____
Diameter	<u>9"</u>	<u>6"</u>	_____
Bearing	<u>N 5° E</u>	<u>S 24° W</u>	_____
Distance	<u>33.6'</u>	<u>50.8'</u>	_____

Bearing Trees, Reference Objects

Species	<u>White Spruce</u>	<u>Birch</u>	_____
Diameter	<u>10"</u>	<u>10"</u>	_____
Bearing	<u>N 53° E</u>	<u>N 73° W</u>	_____
Distance	<u>54.33'</u>	<u>14.55'</u>	_____

Subsequent Corner Restoration

Year surveyed 10/2017 By CCHD/SO
Location filed: #2017.017
Monument: Found USFS brass cap iron pipe up 1.6', at W. edge of junkpile and witnesses as follows.
12" Spruce, N 53° E, 54.33'(1984) 20d nail, up 0.5', S. side
6" Maple, S 58° E, 75.43' duplex nail, up 1.0', N. side
12" Maple, S 72° W, 57.79' duplex nail, up 1.0', S. side

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

T-13

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Jim Parker - 1985
Set obliterated - 2 1/2 x 60" I.P. w/ masked brass cap
10" w. Spruce N53°E 54.33'
10" Birch N73°W 14.55'
Doc. # 281948

Remuneration certificate prepared _____ By _____
Filed at _____ Date _____

CASS COUNTY LAND CORNER RECORD


Index No. T 13

T 144 R 25 M. 5TH Coordinates: X _____ Y _____
Corner common to sections 27/28 E 1/4 28

EXISTING SURVEYS

Original Evidence Found _____
Year of search _____ By _____
Monument found _____

Original Government Survey
Year surveyed 1876
Original monument lost



Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees

Species Aspen 6"
Diameter 7"
Bearing W. Pine
Distance 80'KS
Bearing N30E
Diameter N75W
Distance 11'KS

Subsequent Corner Restoration

Year surveyed 1908 By JAMES FLYNN
Location filed COUNTY BOOK 2 P. 183
Monument Two old Govt B.T.; 7" W. Pine N75W 11'KS

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species W. Pine 9"
Diameter 6"
Bearing W. Pine
Distance 50.8'
Bearing N5E
Diameter S24W
Distance 33.6'

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____