

T. 144 R. 25 M. 5th Coordinates: X _____ Y _____
N 1/4 33 Corner common to sections 28, 33



EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed <u>1876</u>		Year of search _____ by _____	
Original monument <u>Post</u>		Monument found _____	

Bearing Trees	
Species	<u>Birch</u> <u>Aspen</u>
Diameter	<u>6"</u> <u>4"</u>
Bearing	<u>S 22° W</u> <u>N 5° W</u>
Distance	<u>6 links</u> <u>4 links</u>

Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 12/1983 By J.R. Worcester, CCHD
 Location filed: S.P. 11-603-07
 Monument:
 Indicates corner assumed at Station 311+97.81

Evidence of Subsequent Corner Restoration

Year of search 9/1984 By J.H. Parker, LS 9235
 Location filed: Certificate of Location
 Monument: Set 5/8"x 36" aluminum rod monument with cap, at the lost position, 3'+, - south of the south edge of bituminous.

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

Species	<u>Birch</u>	<u>N. Pine</u>
Diameter	<u>9"</u>	<u>12"</u>
Bearing	<u>N 37° E</u>	<u>S 14° E</u>
Distance	<u>125.68'</u>	<u>71.00'</u>

Subsequent Corner Restoration

Year surveyed 7/2011 By CCHD/SO
 Location filed: #2011.015
 Monument: Found P.K. from 1984 witnesses
14'+, - S. of center line CSAH #3 and witnesses as follows.
11" Birch, N 37° E, 125.68'(1984) 20d nail, up 1.4', W. side
14" N. Pine, S 14° E, 71.00'(1984) 20d nail, up 1.3', W. side
12" W. Pine, S 48° W, 92.91' duplex nail, up 1.0', S. side

8/2011, CCHD/SO
#2011.015
Set Mag nail from witnesses after construction, 14.5' south of new center line CSAH #3.

10/2017, CCHD/SO
#2017.017
Found 2011 concrete nail, in good condition 14.5', S. of centerline CSAH #3 and 1984 and 2011 witnesses are good.

7/2019, CCHD/SO
#2017.017
Replaced Conc. nail with Alum. Co. mon., down 0.05', 14'+/-, S. of centerline CSAH #3. 1984 and 2011 witnesses are good.

7/2019, T.L. Freeman, LS 21367
Certificate of Location, A000651790
Filed on the above information.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Monument
Location filed
Year surveyed

By _____

Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Bearing Trees
Species
Diameter 6"
Bearing N5W
Distance 6LKS
4LKS

Original Government Survey
Year surveyed 1876
Original monument lost

EXISTING SURVEYS

Original Evidence Found
Year of search By _____
Monument found _____

Original Bearing Trees Found

Species
Diameter
Bearing
Distance

Evidence of Subsequent Corner Restoration


Year of search By _____

Bearing Trees, Reference Objects

Index No. V 11

CASS COUNTY LAND CORNER RECORD

Coordinates: X 28133
M 57H
R 25
N 144 33
Corner common to sections



Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Jim Parker - 1985
Set lost - 5/8" x 36" aluminum rod w/ stamped cap.
9" Birch N37°E 125.68'
12" N. Pine S14°E 71.00'
Doc. # 281975

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____

V-11