


T. 144 R. 25 M. 5th Coordinates: X _____ Y _____

N 1/4 35 Corner common to sections 26, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1876
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Aspen</u>	<u>Aspen</u>	_____
Diameter	<u>6"</u>	<u>5"</u>	_____
Bearing	<u>S 88° W</u>	<u>N 71° W</u>	_____
Distance	<u>26 links</u>	<u>27 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 12/1983 By J.R. Worcester, CCHD
Location filed:
Monument: S.P. 11-603-06
Indicates corner assumed on centerline at Station 418+33

Evidence of Subsequent Corner Restoration

Year of search 9/1984 By J.H. Parker, LS 9235
Location filed: Certificate of Location
Monument: Set 2.5" iron pipe monument with brass cap, down 0.3' on center line CSAH #3, at obliterated position using feature call to river and centerline of CSAH #3.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>Birch</u>	<u>Ash</u>	_____
Diameter	<u>10"</u>	<u>12"</u>	_____
Bearing	<u>N 36° W</u>	<u>S 52° E</u>	_____
Distance	<u>64.46'</u>	<u>125.47'</u>	_____

Subsequent Corner Restoration

Year surveyed 7/2011 By CCHD/SO
Location filed: #2011.015
Monument: Found USFS brass cap monument down 0.7' on center line CSAH #3, 199'+, - west of bridge.
10" Cedar, S 23° E, 60.21'
24" B. Oak, S 52° W, 120.34'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

8/2011, CCHD/SO
#2011.015
Set Mag nail from witnesses after construction, 0.5' north of new center line CSAH #3.

7/2019, CCHD/SO
#2011.015
Found Conc. nail, 0.5', N. of centerline CSAH #3. 1984 and 2011 witnesses are good.

7/2019, T.L. Freeman, LS 21367
Certificate of Location, A000651793
Filed on the above information.

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Year surveyed
Location filed
Monument

By

Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Bearing Trees

Species
Diameter
Bearing
Distance
Aspen 6"
Aspen 5"
S88W N71W
86Ks 27Ks

Year surveyed
Original monument

1876

lost

Original Government Survey

EXISTING SURVEYS

Index No. V 19
T. 144 R. 25 M. 5TH Coordinates: X 86135 Y
Corner common to sections

CASS COUNTY LAND CORNER RECORD

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Tim Parker - 1985
Set lost - 2 1/2" I.P. w/ stamped brass cap
10" Birch - N36°W 64.46'
12" Ash 55°E 125.47'
Doc # 281779

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____



Original Evidence Found
Year of search _____ By _____
Monument found _____
Original Bearing Trees Found

Species
Diameter
Bearing
Distance

Evidence of Subsequent Corner Restoration

By

Year of search

Bearing Trees, Reference Objects