

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Year surveyed _____
Location filed _____
Monument _____

By _____

Subsequent Corner Restoration

Species Willow 12"
Diameter 12"
Bearing N 38 W
Distance 56 ft
80 ft
54 ft

Bearing Trees

Year surveyed 1876
Original monument lost

Original Government Survey

EXISTING SURVEYS

T. 144 R. 25 M. 5TH Coordinates: X 76.35 Y _____
Corner common to sections 26, 35
M C # 55

CASS COUNTY LAND CORNER RECORD

Index No. V 19-20


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____



Original Evidence Found _____
Year of search _____ By _____
Monument found _____
Original Bearing Trees Found _____
Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects