


T. 144 R. 25 M. 5th Coordinates: X _____ Y _____

N 1/4 31 Corner common to sections 30, 31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1876
Original monument Post

Original Evidence Found

Year of search 1914 by Donner
Monument found Fd BT
Survey Rec #485, Bk C, pg 547

Bearing Trees

Species	<u>Balsam</u>	<u>Lynn</u>
Diameter	<u>8"</u>	<u>16"</u>
Bearing	<u>N 19° W</u>	<u>S 13° E</u>
Distance	<u>37 links</u>	<u>83 links</u>

Original Bearing Trees Found

Species	<u>Basswood</u>		
Diameter			
Bearing	<u>S 14° E</u>		
Distance	<u>21.6'</u>		

Subsequent Corner Restoration

Year surveyed 9/1914 By F.A. Donner
Location filed: Survey Record #485, Book C, page 547 and Curo Monument: Hub Curo Book 94, page 4 and Donner Book, page 138

Evidence of Subsequent Corner Restoration

Year of search 12/1983 By J.R. Worcester, CCHD
Location filed: S.P. 11-603-07
Monument: Indicates corner assumed at intersection of roads Station 205+75.81 and witnesses

Bearing Trees, Reference Objects

Species			
Diameter			
Bearing			
Distance			

Bearing Trees, Reference Objects

Species	<u>P. Pole</u>	<u>Elm</u>	<u>Pop.</u>
Diameter		<u>12"</u>	<u>6"</u>
Bearing	<u>North</u>	<u>S W</u>	<u>S E</u>
Distance	<u>60.4'</u>	<u>63.0'</u>	<u>68.0'</u>

Subsequent Corner Restoration

Year surveyed 1984 By J.H. Parker, LS 9235
Location filed: Certificate of Location
Monument: Set 5/8"x 36" aluminum rod monument with cap, down 0.3' at obliterated position, on center line of CSAH #3 and center line of Township Road to S. and fence line to N. 14" Maple, N 6° E, 83.47' 8" Basswood, S 55° E, 113.51'

Evidence of Subsequent Corner Restoration Found

Year of search 7/2019 By T.L. Freeman, LS 21367
Location filed: Certificate of Location, A000651786
Monument: Mag nail found over aluminum rod
Filed certificate on the previous information.

7/2011, CCHD/SO #2011.015
Found aluminum rod, down 1.5' top 0.3' bent, on center line of CSAH #3, 3'+, - west of center line 74th Ave. and add the following:
17" Maple, N 6° E, 83.24'(1984)
8" Maple, S 48° E, 121.43'
8" N. Pine, S 42° W, 72.04'

8/2011, CCHD/SO #2011.015
Set Mag nail from witnesses after construction, on new center line CSAH #3.

7/2019, CCHD/SO #2011.015
Found Conc. nail, on centerline CSAH #3. 1984 and 2011 witnesses are good.

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

also on microf. film - roll 115 BK94 R4

Year surveyed 1914
Location filed County Book 2nd P. 547
By F.A. Danner
Monument 8" Basswood

Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Bearing Trees
8" Basswood
8" Basswood
N19W
S13E
37 LKS
83 LKS

Year surveyed 1876
Original monument lost

Original Government Survey

EXISTING SURVEYS

Coordinates: X 144 R 25 M 577
Y 30131
114 31 corner common to sections

CASS COUNTY LAND CORNER RECORD

Index No. V3

Bearing Trees, Reference Objects

Year of search _____ By _____


Evidence of Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Original Bearing Trees Found

Year of search _____ By _____
Original Evidence Found
Monument found _____

O = Corner



Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Jim Parker - 1985
Set obliterated - 5/8 x 36" aluminum rod w/ cap
14" Maple N6°E 83.47'
8" Basswood S55°E 113.51'
Doc. # 281971

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____