

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Monument

Year surveyed
Location filed

By

Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

19m Spruce
8" 4"
14 LKS
N43E
N68W
15 LKS

Original monument Post
Year surveyed 1876
Original Government Survey

EXISTING SURVEYS

Coordinates: X 144 R. 25 M. 5TH
Corner common to sections 31, 32
Y

CASS COUNTY LAND CORNER RECORD

Index No. X5

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Jim Parker - 1985
Set lost - 2 1/2" lip w/ stamped brass cap
12" Cedar S42E 27.95'
9" Cedar S89W 32.73'
Doc. # 28981


Bearing Trees, Reference Objects

Evidence of Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Original Bearing Trees Found
Year of search _____ By _____
Monument found _____
Original Evidence Found

O = Corner



Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____