


Index No. J 11

CASS COUNTY LAND CORNER RECORD

T. 144 R. 26 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N114 16 Corner common to sections 9, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species Tam  
Diameter 5"  
Bearing N76E  
Distance 106 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1971 By William Okerman  
Location filed \_\_\_\_\_  
Monument Set 2" x 1/2" galvanized steel pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>Blk Spruce</u>	<u>Blk Spruce</u>	<u>Blk Spruce</u>
Diameter	<u>4"</u>	<u>5"</u>	<u>4"</u>
Bearing	<u>S58W</u>	<u>S24E</u>	<u>N46E</u>
Distance	<u>11.80'</u>	<u>17.80'</u>	<u>19.90'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1971 - FILED IN 1979  
Doc. # 258564

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_