


T. 144 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 15 Corner common to sections 10, 11, 14, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	Tam	Oak	Tam	Spruce
Diameter	8"	5"	6"	10"
Bearing	S13E	S10W	N48E	N14W
Distance	28 LKS	20 LKS	15 LKS	17 LKS

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1970 By William Okerman  
Location filed \_\_\_\_\_  
Monument Set 5 1/2" x 5 1/2" x 60" concrete monument with brass cap  
Cedar post 4x4x72" North 3.40'  
Treated post 4" East 2.60'

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	Elm	Elm	W. Oak
Diameter	6"	11"	17"
Bearing	N40E	S19E	N41W
Distance	23.50'	33.60'	26.40'

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1970