


Index No. J 19

CASS COUNTY LAND CORNER RECORD

T. 144 R. 26 M. 57H Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 19 Corner common to sections 11, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Cedar</u>	<u>Cedar</u>	_____	_____
Diameter	<u>5"</u>	<u>5"</u>	_____	_____
Bearing	<u>N 54 W</u>	<u>S 23 E</u>	_____	_____
Distance	<u>5 LKS</u>	<u>11 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1970 By William Okerman  
Location filed \_\_\_\_\_  
Monument Set 2" x 60" galvanized steel pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>	_____
Diameter	<u>6"</u>	<u>7"</u>	<u>5"</u>	_____
Bearing	<u>S 70 W</u>	<u>S 18 W</u>	<u>N 42 E</u>	_____
Distance	<u>17.50'</u>	<u>15.70'</u>	<u>18.30'</u>	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1970

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_