


Index No. L13

CASS COUNTY LAND CORNER RECORD

T. 144 R. 26 M. 5TH Coordinates: X _____ Y _____
E 1/4 16 Corner common to sections B, 16



o = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	Bearing	Distance
<u>Tam Spruce</u>	<u>59E</u>	<u>18 Lks</u>
<u>Spruce</u>	<u>59E</u>	<u>20 Lks</u>

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1971 By William Okerman
Location filed _____
Monument Set 2"x60" galvanized steel pipe
with brass cap.
Treated post 4" North 1.60"

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Tamarack</u>	<u>N51W</u>	<u>9.20'</u>
<u>Cedar</u>	<u>N71E</u>	<u>31.70'</u>
<u>Cedar</u>	<u>554E</u>	<u>23.20'</u>
<u>Cedar</u>	<u>S23W</u>	<u>21.70'</u>

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1971 - FILED IN 1979
Doc. # 258567

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____