


T. 144 R. 26 M. 5th Coordinates: X _____ Y _____
E 1/4 13 Corner common to sections 12,13 and 7,18/144/25



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search 1912 by H. Todd
Monument found Set stake
Survey Rec #211, Bk A, pg 517

Bearing Trees

Species Cedar Cedar
Diameter 8" 5"
Bearing N 85° W East
Distance 6 links 7 links

Original Bearing Trees Found

Species Cedar
Diameter 5"
Bearing East
Distance 7 links

Subsequent Corner Restoration

Year surveyed 3/1912 By H.S. Todd
Location filed: Survey Record #211, Book A, page 517 and Curo
Monument: Set from GLO
Curo Book 98, page 81

Evidence of Subsequent Corner Restoration

Year of search 7/1919 By J.H. Flynn
Location filed: Survey Record #415, Book C, page 178
Monument:
Nothing found or set by him.

Bearing Trees, Reference Objects

Species Cedar Cedar
Diameter 8" 12"
Bearing N 75° E S 70° E
Distance 19.80' 35.10'

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 12/1983 By J.R. Worcester, CCHD
Location filed: S.P. 11-603-05
Monument:
Corner assumed at Station 47+74.1

10/1984, J.H. Parker, LS 9235
Set 5/8"x 36" aluminum rod monument with cap, at lost
position, down 0.3' on center line of County Road #3 and
witnessed as follows:
12" Cedar, N 85° W, 71.10'
6" Balsam, S 57° W, 81.53'

7/2011, CCHD/SO
#2011.015
Found P.K. from 1985 witnesses, 18'+,- west of center line Co.
Rd. #3 and add the following:
P. Pole, N 4° W, 237.20'

8/2011, CCHD/SO
#2011.015
Replace P.K. with Mag nail from witnesses after construction,
1.0' west of new bituminous CSAH #3.

Evidence of Subsequent Corner Restoration Found


Year of search 7/2019 By CCHD/SO
Location filed: #2011.015
Monument: Found magnetic concrete nail
replaced with Alum. Co. Mon., down 0.05' foot, 18'+,-, W. of
centerline CSAH #3 and recovered the 1985 and 2011
witnesses.

7/2019, T.L. Freeman, LS 21367
Certificate of Location, A000651780
Filed on the above information.

Index No. L 25

CASS COUNTY LAND CORNER RECORD

T. 144 R. 26 M. 574 Coordinates: X _____ Y _____
E 1/4 13 Corner common to sections 13 AND 18-144-25



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Cedar</u>	<u>Cedar</u>	_____	_____
Diameter	<u>8"</u>	<u>5"</u>	_____	_____
Bearing	<u>N 85W</u>	<u>East</u>	_____	_____
Distance	<u>6 LKS</u>	<u>7 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By HARRY S. TODD
Location filed COUNTY SURVEY RECORD BOOK "A" P516-518
Monument FOUND OLD GOVT B.T.: 5" CEDAR EAST 7 LKS. SET STAKE

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>CEDAR</u>	<u>CEDAR</u>	_____	_____
Diameter	<u>8"</u>	<u>12"</u>	_____	_____
Bearing	<u>N 75E</u>	<u>S 70E</u>	_____	_____
Distance	<u>19.80'</u>	<u>35.10'</u>	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Jim Parker - 1985
Set lost - set 5/8 x 36" aluminum rod w/cap
6" Bakam S 57° W 81.53'
12" Cedar N 85° W 71.10'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____