


Index No. N 9

CASS COUNTY LAND CORNER RECORD

T. 144 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 20 Corner common to sections 16, 17, 20, 21



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1875  
 Original monument Post

| Bearing Trees |                |                |                |
|---------------|----------------|----------------|----------------|
| Species       | Cedar          | Tam            | N. Pine        |
| Diameter      | <u>8"</u>      | <u>3"</u>      | <u>8"</u>      |
| Bearing       | <u>S77W</u>    | <u>N78W</u>    | <u>S85E</u>    |
| Distance      | <u>116 LKS</u> | <u>117 LKS</u> | <u>265 LKS</u> |

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
|         |          |         |          |
|         |          |         |          |
|         |          |         |          |

**Subsequent Corner Restoration**  
 Year surveyed 1971 By William Okerman  
 Location filed \_\_\_\_\_  
 Monument Set 2" x 160" galvanized steel pipe with brass cap.

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

| Species  | Cedar         | Tamarack      | Tamarack      | Black Spruce  |
|----------|---------------|---------------|---------------|---------------|
| Diameter | <u>13"</u>    | <u>5"</u>     | <u>4"</u>     | <u>6"</u>     |
| Bearing  | <u>N80W</u>   | <u>N35E</u>   | <u>S71E</u>   | <u>S66W</u>   |
| Distance | <u>77.50'</u> | <u>21.50'</u> | <u>13.80'</u> | <u>53.70'</u> |

**Bearing Trees, Reference Objects**

| Species      | Diameter   | Bearing     | Distance      |
|--------------|------------|-------------|---------------|
| <u>Cedar</u> | <u>14"</u> | <u>S77W</u> | <u>76.60'</u> |
|              |            |             |               |
|              |            |             |               |

(1875 BT)

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1971 - FILED IN 1979  
Doc. # 258569

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_