


Index No. P13

CASS COUNTY LAND CORNER RECORD

T. 144 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 21 Corner common to sections 21, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Tree
<u>Cedar</u>	<u>Cedar</u>	
<u>10"</u>	<u>4"</u>	
<u>N52E</u>	<u>N67W</u>	
<u>94S</u>	<u>94S</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1970 By William Okerman  
Location filed \_\_\_\_\_  
Monument Set 5 1/2" x 5 1/2" x 60" concrete monument with brass cap.  
Cedar post 4" x 72" North 3.20'

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	Bearing	Tree	Distance
<u>Cedar</u>	<u>Cedar</u>	<u>Ash</u>	
<u>14"</u>	<u>6"</u>	<u>6"</u>	
<u>S70E</u>	<u>N58W</u>	<u>N7E</u>	
<u>18.40'</u>	<u>42.10'</u>	<u>35.70'</u>	

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1970 - FILED IN 1979  
Doc. # 258572

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_