


T. 144 R. 26 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

E 1/4 24 Corner common to sections 24 and 19/144/25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>W. Pine</u>	<u>Birch</u>	_____
Diameter	<u>30"</u>	<u>12"</u>	_____
Bearing	<u>S 69° W</u>	<u>S 55° E</u>	_____
Distance	<u>10 links</u>	<u>10 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 2/1903 By O.C. Gilbert  
Location filed: Road Calendar A, page 44  
Monument:  
Zuzu-Bear River Road, indicates corner position in road.  
This information also in Road Calendar B, page 30

Evidence of Subsequent Corner Restoration

Year of search 3/1912 By H.S. Todd  
Location filed: Survey Record #211, Book A, page 517 and Curo  
Monument: Gone  
Curo Book 98, page 80, corner and bearing trees gone.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 12/1913 By J.W. Curo, LS 1428  
Location filed: Survey Record #322, Book B, page 413  
Monument:  
Surveyed Range line and marked centerline of State Road #6,  
no mention of setting corner.

Evidence of Subsequent Corner Restoration Found

Year of search 8/2011 By CCHD/SO  
Location filed: #2011.015  
Monument: Set Mag nail  
from witnesses after construction, 1.0'+, - west of new centerline  
CSAH #3.

12/1983, J.R. Worcester, CCHD  
S.P. 11-603-05  
Indicates corner assumed at Station 101+07.5  
  
10/1984, J.H. Parker, LS 9235  
Certificate of Location  
Set 5/8"x 36" aluminum rod monument with cap, at obliterated  
position at extension of fence lines and witnessed.  
P. Pole, S 40° W, 68.80'  
Steel Fence, Post S 55° E, 74.15'


7/2019, CCHD/SO  
#2011.015  
Found Conc. nail, 1.0', W. of centerline CSAH #3. 1984 and  
2011 witnesses are good.  
  
7/2019, T.L. Freeman, LS 21367  
Certificate of Location, A000651782  
Filed on the above information.

7/2011, CCHD/SO  
#2011.015  
Excavate 2'x 1.5' hole, found aluminum rod, down 1.4', top 0.5'  
bent, 1.5'+, - west of center line Co. Rd. #3 and add the  
following:  
P. Pole S 40° W, 69.53'  
10" Aspen N 63° W, 121.22'  
Fence Post S 84° E, 57.58'

Index No. P 25

CASS COUNTY LAND CORNER RECORD

T. 144 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 24 Corner common to sections 24 and 19-144-25



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species w. Pine Birch  
Diameter 30" 12"  
Bearing S 69° W S 55° E  
Distance 10 LKS 10 LKS

ENTER NARROW Pine Ridge

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration P 25

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Jim Parker - 1965  
Set obliterated - 5/8" x 36" aluminum rod w/ cap  
top, steel fence post S 55° E 74.15'  
Power Pole S 40° W 68.80'  
Doc. # 281948

1999 - CCSO

End. Inpl. P.K. 1.5' N & Co. RD. 3 and  
37' N of E Rd. to the west. Is also in line  
w/ fe. to the east.

REF. TIES:

9" Aspen (clump of 3) N 68° W 127.42'  
P. Pole S 40° W 69.39'  
top steel fence post S 55° E 74.15'  
Fence COR. POST S 84° E 57.34'

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_