


Index No. R 21

CASS COUNTY LAND CORNER RECORD

T. 144 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 26 Corner common to sections 23, 24, 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>Cedar</u>	<u>Cedar</u>	<u>Aspen</u>	<u>Sugar</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>10"</u>	<u>5"</u>
Bearing	<u>N30W</u>	<u>N22E</u>	<u>S38E</u>	<u>S61W</u>
Distance	<u>13LKS</u>	<u>33LKS</u>	<u>9LKS</u>	<u>9LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1953 By R.W. Fassett
Location filed USFS
Monument Set Temp stake at point of intersection

Evidence of Subsequent Corner Restoration

Year of search 1969 By C. Krause
Fd 2"x2" stake rotted at ground. No evidence found around fence corner north of stake.

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>Aspen</u>	<u>Aspen</u>
Diameter	<u>14"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>N69°W</u>	<u>N6°E</u>	<u>S9°E</u>
Distance	<u>29.04'</u>	<u>5.94'</u>	<u>9.90'</u>

Bearing Trees, Reference Objects

Species	<u>Elm</u>	_____	_____
Diameter	<u>17"</u>	_____	_____
Bearing	<u>N69°W</u>	_____	_____
Distance	<u>29.04'</u>	_____	_____

Subsequent Corner Restoration R 21

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____