


Index No. R5

CASS COUNTY LAND CORNER RECORD

T. 144 R. 26 M. 574 Coordinates: X _____ Y _____
NE 30 Corner common to sections 19, 20, 29, 30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	Birch	Cedar	Cedar	White
Diameter	5"	6"	8"	10"
Bearing	S37W	S57E	N41E	N84W
Distance	8 LKS	22 LKS	14 LKS	20 LKS

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By GLO
Location filed Sec. of State
Monument Set 2x36" I.P. w/ brass cap at intersection
of blazed lines N, S, E & W T144N R26W
519/520
530/529

Evidence of Subsequent Corner Restoration

Year of search 1970 By Milo Stefan
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	Br. Oak	Spruce	Cedar	Ash
Diameter	9"	7"	6"	11"
Bearing	N19-30E	S14-45E	S20W	N7-30W
Distance	144 LKS	319 LKS	210 LKS	127 LKS

Bearing Trees, Reference Objects

W. Oak	W. Spruce
6"	6"
N 41W	S 72E
19.00'	22.30'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN 1970 - FILED IN 1979
Doc. # 246221

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____