


Index No. X-49

CASS COUNTY LAND CORNER RECORD

T. 144 R. 26 M. 5TH Coordinates: X _____ Y _____

ML Corner common to sections 32, 33

S. Side dredged channel



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1922
Original monument 4x4x6' cedar post
4' in ground

Bearing Trees

Species _____
Diameter NO B.T.S.
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____