


Index No. C17

CASS COUNTY LAND CORNER RECORD

T. 144 R. 27 M. 5TH Coordinates: X _____ Y _____
E 1/4 3 Corner common to sections 2, 3



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Tam Tam
Diameter 5" 4"
Bearing S19 1/2 W N56 E
Distance 63 LKS 29 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1937 By GLO
Location filed SEC. OF STATE
Monument End tam stake stumps of both B.T.S. Set
1x36" L.P. w/ brass cap
1/4
53/52
1937

Evidence of Subsequent Corner Restoration

Year of search 1977 By Milo Stefan
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species Tam Tam
Diameter 7" 8"
Bearing N48 3/4 E S79 3/4 W
Distance 56 LKS 85 LKS

Bearing Trees, Reference Objects

Cedar Cedar Tamarack
9" 9" 9"
N63 E S43 E N87 W
81.40' 37.80' 88.20'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1977
Doc. # 258584

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____