


T. 144 R. 27 M. 5TH Coordinates: X _____ Y _____
N 114 15 Corner common to sections 10, 15



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Bearing Trees

Species Tam stub
Diameter 8"
Bearing N 20 E
Distance 16 LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1937 By GLO
Location filed Sec. of State
Monument Set 1x36" i.p. w/ brass cap 11 510
14 515
1937

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	<u>Tam</u>	<u>Tam</u>
Diameter	<u>9"</u>	<u>8"</u>
Bearing	<u>S 22 W</u>	<u>N 43 3/4 W</u>
Distance	<u>297 LKS</u>	<u>174 LKS</u>

Bearing Trees, Reference Objects

Species	<u>Poplar</u>	<u>Poplar</u>
Diameter	<u>8"</u>	<u>9"</u>
Bearing	<u>S 78 E</u>	<u>N 82 E</u>
Distance	<u>81.3'</u>	<u>114.7'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - OKERMAN - 1966