


T. 144 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 18 Corner common to sections 7, 8, 17, 18



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1873  
 Original monument Post

| Species       | Bearing       | Trees         |
|---------------|---------------|---------------|
| <u>Poplar</u> | <u>Poplar</u> | <u>Poplar</u> |
| <u>5"</u>     | <u>20"</u>    | <u>6"</u>     |
| <u>N88E</u>   | <u>N9W</u>    | <u>S50E</u>   |
| <u>16 LKS</u> | <u>6 LKS</u>  | <u>33 LKS</u> |

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found

| Species | Bearing | Distance |
|---------|---------|----------|
| _____   | _____   | _____    |
| _____   | _____   | _____    |
| _____   | _____   | _____    |
| _____   | _____   | _____    |

Subsequent Corner Restoration  
 Year surveyed 1937 By GLD  
 Location filed Sec. of state  
 Monument Find remains of all 4 B.T.S. - Set concrete  
Mon. 2' long 6" Dia. wireless cap T144W R27W  
57/58  
318/517  
1937

| Species          | Bearing        | Trees            | Reference Objects |
|------------------|----------------|------------------|-------------------|
| <u>N. Pine</u>   | <u>R. Oak</u>  | <u>Osage</u>     | <u>Cedar</u>      |
| <u>8"</u>        | <u>9"</u>      | <u>6"</u>        | <u>8"</u>         |
| <u>N15 1/4 E</u> | <u>S59E</u>    | <u>S24 1/2 W</u> | <u>N61W</u>       |
| <u>22 LKS</u>    | <u>102 LKS</u> | <u>57 LKS</u>    | <u>199 LKS</u>    |

Evidence of Subsequent Corner Restoration  
 Year of search 1964 By William Okerman  
Set 6" x 60" cylindrical concrete  
monument with 3" stamped bronze  
tablet.

Bearing Trees, Reference Objects

| Species      | Bearing       | Distance      |
|--------------|---------------|---------------|
| <u>Elm</u>   | <u>Elm</u>    | <u>Elm</u>    |
| <u>6"</u>    | <u>11"</u>    | <u>10"</u>    |
| <u>N50E</u>  | <u>N7E</u>    | <u>S48E</u>   |
| <u>63.4'</u> | <u>110.1'</u> | <u>151.5'</u> |

Cedar Post  
4x4x60"  
North  
14.0'

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - OKERMAN, 1964  
1994, 10-31 By: Terry Freeman  
Found a 1964 6" x 60" cylindrical concrete  
monument w/ stamped brass cap. left as found  
3-16-95 Cert. Filed by: Terry Freeman, RLS 21367,  
Doc. # 365391.  
Elm - 11" - N7E - 110.1; Norway Pine - 7" - N45E -  
6.44; Norway Pine - 8" - N47W - 17.64;  
Norway Pine - 6" - S78W - 38.03; Norway  
Pine - 4" - S28E - 14.12