Index No. J 5-6

CASS COUNTY LAND CORNER RECORD

T. 144 R. 27 M. 5TH Coordinates: X _____ Y _____

MC# 11 Corner common to sections 8, 17



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Cedar	Cedar		
Diameter	8"	8"		
Bearing	S3W	S73W		
Distance	16 LKS	18 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1937 By GLO

Location filed Sec. of State

Monument Fnd both BTs = now 12" & 14" - Corner falls in lake - Set W.C. MC. 1x36" 1.P. w/brass cap 0.64 CH

T144N
S8 | MC
S17 | WC
R27W
1937

Bearing Trees, Reference Objects

Species	Cedar	Cedar		
Diameter	8"	6"		
Bearing	S34½E	N43W		
Distance	45 LKS	24 LKS		

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____