


T. 144 R. 27 M. 5th Coordinates: X _____ Y _____
MC# 10 Corner common to sections 8, 17



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	_____
Diameter	<u>6"</u>	<u>6"</u>	_____
Bearing	<u>East</u>	<u>N74E</u>	_____
Distance	<u>100 LKs</u>	<u>79 LKs</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By GLO
Location filed Sec. of State
Monument Set 1x36" l.p. Wilbress cap T144W

Evidence of Subsequent Corner Restoration

Year of search 1964 By William Okerman
Set 5' x 2" galvanized steel post filled with concrete and capped with 3" stamped bronze tablet.

Bearing Trees, Reference Objects

Species	<u>Birch</u>	<u>Poplar</u>	_____
Diameter	<u>6</u>	<u>10</u>	_____
Bearing	<u>N64E</u>	<u>S39 1/2 E</u>	_____
Distance	<u>142 LKs</u>	<u>240 LKs</u>	_____

Bearing Trees, Reference Objects

Cedar Post	Cedar Post	_____
<u>4"x4"x60"</u>	<u>4"x4"x60"</u>	_____
<u>East</u>	<u>37° East</u>	_____
<u>7.2'</u>	<u>8.2'</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - OKERMAN - 1964