


T. 144 R. 27 M. 5TH Coordinates: X _____ Y _____
E 13 Corner common to sections 13 AND 18-144-26



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument Post

Bearing Trees
 Species N. Pine
 Diameter 24"
 Bearing North
 Distance 50 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

O = Corner

Subsequent Corner Restoration
 Year surveyed 1937 By GLO
 Location filed Sec. of State
 Monument Set 1x36" 1/4. willow cap 1/4
513/518
1937

Evidence of Subsequent Corner Restoration
 Year of search 1966 By William Okerman
Found GLO monument in good condition
Found GLO BT's in good condition.

Bearing Trees, Reference Objects
 Species N. Pine N. Pine
 Diameter 12" 12"
 Bearing N15E S85W
 Distance 57 LKS 30 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - OKERMAN - 1966