


Index No. L5

CASS COUNTY LAND CORNER RECORD

T. 144 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 18 Corner common to sections 17, 18



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument lost

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>N. Pine</u>	<u>N. Pine</u>	_____	_____
Diameter	<u>12"</u>	<u>12"</u>	_____	_____
Bearing	<u>W 82° E</u>	<u>N 80° E</u>	_____	_____
Distance	<u>18 LKS</u>	<u>21 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By GLO  
Location filed Sec. of state  
Monument Set 1x36" l.p. Wilcox cap 114  
Corner at N. end of open marsh 518/517  
1937

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman  
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>N. Pine</u>	_____	_____
Diameter	<u>23"</u>	<u>18"</u>	_____	_____
Bearing	<u>N 75 1/2° E</u>	<u>N 27 1/2° W</u>	_____	_____
Distance	<u>202 LKS</u>	<u>117 LKS</u>	_____	_____

Bearing Trees, Reference Objects

<u>OAK</u>	<u>Elm</u>	_____	_____
<u>4"</u>	<u>5"</u>	_____	_____
<u>N 78° E</u>	<u>N 40° W</u>	_____	_____
<u>53.15'</u>	<u>52.9'</u>	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - OKERMAN - 1966

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_