


Index No. N15

CASS COUNTY LAND CORNER RECORD

T. 144 R. 27 M. 5TH Coordinates: X _____ Y _____
N14 22 Corner common to sections 15, 22



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees	
<u>Poplar</u>	<u>Poplar</u>	
Diameter <u>6"</u>	<u>7"</u>	
Bearing <u>N10E</u>	<u>S15W</u>	
Distance <u>15 LKS</u>	<u>14 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By GLO
Location filed Sec. of State
Monument Set 1x36" l.p. brass cap 11/5/37
1/5/37
1937

Evidence of Subsequent Corner Restoration

Year of search 1966 By Milo Stefan
Found GLO monument in good condition

Species	Bearing Trees, Reference Objects	
<u>White Pine</u>	<u>E/ln</u>	
Diameter <u>15"</u>	<u>6"</u>	
Bearing <u>N37 1/4 E</u>	<u>S76 3/4 W</u>	
Distance <u>346 LKS</u>	<u>77 LKS</u>	

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Birch</u>	<u>5"</u>	<u>S20E</u>	<u>41.95'</u>
<u>Red Pine</u>	<u>9"</u>	<u>N58E</u>	<u>39.65'</u>
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1966 - FILED IN 1980
Doc. # 258583

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____