


Index No. N19

CASS COUNTY LAND CORNER RECORD

T. 144 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1423 Corner common to sections 14, 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species Poplar \_\_\_\_\_  
Diameter 6" \_\_\_\_\_  
Bearing N55E \_\_\_\_\_  
Distance 60 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1937 By GLO  
Location filed Sec. of State  
Monument Set 1x36" l.p. w/ brass cap 11, 514  
14, 523  
1937

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species N. Pine N. Pine \_\_\_\_\_  
Diameter 7" 8" \_\_\_\_\_  
Bearing S2E N84 3/4 W \_\_\_\_\_  
Distance 206 LKS 186 LKS \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_