


T. 144 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 24 Corner common to sections 13, 24 and 18, 19-144-26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>B1. Pine</u>	<u>N. Pine</u>	<u>Poplar</u>	<u>N. Pine</u>
Diameter	<u>8"</u>	<u>6"</u>	<u>4"</u>	<u>10"</u>
Bearing	<u>N38W</u>	<u>N68E</u>	<u>N37E</u>	<u>N62W</u>
Distance	<u>22 LKS</u>	<u>60 LKS</u>	<u>70 LKS</u>	<u>53 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By GLO  
Location filed Sec. of State  
Monument Founding B.T.S. NE-now 18", NW-now 16" and  
Stumps of SE & SW Set Concrete mon 2' dia 6" dia  
w/ brass cap

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman  
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>	<u>513 / 518</u>
Diameter	<u>6"</u>	<u>16"</u>	<u>10"</u>	<u>12"</u>
Bearing	<u>N39 1/2 E</u>	<u>S59E</u>	<u>S73 1/4 W</u>	<u>N10 1/2 W</u>
Distance	<u>61 LKS</u>	<u>50 LKS</u>	<u>75 LKS</u>	<u>66 LKS</u>

Bearing Trees, Reference Objects

N. Pine	R. Pine	R. Pine	R. Pine
<u>13"</u>	<u>10"</u>	<u>12"</u>	<u>10"</u>
<u>N39 1/2 E</u>	<u>N37W</u>	<u>S52W</u>	<u>S37E</u>
<u>40.26'</u>	<u>20.25'</u>	<u>33.75'</u>	<u>36.9'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - OKERMAN - 1966