


T. 144 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E11422 Corner common to sections 22,23



○ = Corner

EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1873  
Original monument Post

Bearing Trees	
Species <u>Cedar</u>	<u>Cedar</u>
Diameter <u>5"</u>	<u>3"</u>
Bearing <u>S17W</u>	<u>N11E</u>
Distance <u>13 LKS</u>	<u>19 LKS</u>

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1937 By GLO  
Location filed Sec. of State  
Monument Set 1x36" 11P. w/brass cap 14  
522/523  
1937

**Evidence of Subsequent Corner Restoration**

Year of search 1966 By William Okerman  
Found GLO monument and BT's in good condition.

**Bearing Trees, Reference Objects**

Species <u>Cedar</u>	<u>Ash</u>
Diameter <u>6"</u>	<u>5"</u>
Bearing <u>N49E</u>	<u>N57W</u>
Distance <u>26 LKS</u>	<u>51 LKS</u>

**Bearing Trees, Reference Objects**

_____	_____
_____	_____
_____	_____
_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - OKERMAN - 1966