


Index No. R15

CASS COUNTY LAND CORNER RECORD

T. 144 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1/4 27 Corner common to sections 22, 27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Poplar Poplar  
Diameter 4" 3"  
Bearing S17W N13E  
Distance 9 LKs 11 LKs

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1937 By GLO  
Location filed Sec. of State  
Monument Set 1x36" lip. brass cap 1/4 522  
1/4 527  
1937

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman  
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species Maple Spruce  
Diameter 7" 12"  
Bearing S57E N14 1/2 W  
Distance 29 LKs 62 LKs

Bearing Trees, Reference Objects

Maple Maple  
12" 4"  
S39W N78E  
25.35' 19.82'

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - OKERMAN - 1966

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_