


Index No. R7

CASS COUNTY LAND CORNER RECORD

T. 144 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N<sup>14</sup>29 Corner common to sections 20,29



○ = Corner

EXISTING SURVEYS

Original Government Survey  
Year surveyed 1873  
Original monument Post

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Tam Tam  
Diameter 4" 4"  
Bearing N25W S40W  
Distance 13 LKS 14 LKS

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1937 By GLO  
Location filed Sec. of State  
Monument Set 1x36" 1/8" w/brass cap // 520  
4 529  
1937

Evidence of Subsequent Corner Restoration  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
Species Tam Tam  
Diameter 6" 4"  
Bearing N44 1/2 E S84 1/2 E  
Distance 27 LKS 85 LKS

Bearing Trees, Reference Objects  
\_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - Gurg Stevenson - 1982  
Doc. # 264940  
Found GLO monument in good condition  
8" Tamarack N45E 17.8' (1937 BT);  
9" Tamarack N56E 16.6';  
6" Tamarack S84E 56.1' (1937 BT);  
8" Tamarack N82 W 50.0'

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_