


Index No. V19

CASS COUNTY LAND CORNER RECORD

T. 144 R. 27 M. 5th Coordinates: X _____ Y _____
N¹⁴ 35 Corner common to sections 26, 35



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	<u>Birch</u>	<u>Poplar</u>	Bearing Trees	_____
Diameter	<u>10"</u>	<u>4"</u>	_____	_____
Bearing	<u>S80W</u>	<u>N80W</u>	_____	_____
Distance	<u>8 LKS</u>	<u>10 LKS</u>	_____	_____

Original Bearing Trees Found	_____	_____	_____
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By GLO
Location filed Sec. of State
Monument Set 1x3/8" iron w/ brass cap 1/4" 526
535
1937

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman
Found GLO monument and SE BT in good condition.

Bearing Trees, Reference Objects

Species	<u>Tan</u>	<u>Tan</u>	_____
Diameter	<u>5"</u>	<u>5"</u>	_____
Bearing	<u>S88E</u>	<u>N37 1/4 W</u>	_____
Distance	<u>290 LKS</u>	<u>148 LKS</u>	_____

Bearing Trees, Reference Objects

<u>Tamarack</u>	_____	_____	_____
<u>7"</u>	_____	_____	_____
<u>N38W</u>	_____	_____	_____
<u>110.6'</u>	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - OKERMAN - 1966

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____