


T. 144 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 36 Corner common to sections 25, 36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species		Bearing		Trees	
Species	<u>Poplar</u>	<u>Poplar</u>			
Diameter	<u>4"</u>	<u>3"</u>			
Bearing	<u>S 31 W</u>	<u>S 1 E</u>			
Distance	<u>19 LKS</u>	<u>16 LKS</u>			

Species		Bearing		Trees Found	
Species	_____	_____	_____	_____	_____
Diameter	_____	_____	_____	_____	_____
Bearing	_____	_____	_____	_____	_____
Distance	_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By GLO  
Location filed Sec. of State  
Monument Set 1x36" lip. w/brass cap 1/4 525  
536  
1937

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>Birch</u>			
Diameter	<u>5"</u>	<u>5"</u>			
Bearing	<u>N 3 E</u>	<u>S 24 3/4 W</u>			
Distance	<u>109 LKS</u>	<u>27 1/2 LKS</u>			

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - MILO STEFAN - 1970 - FILED IN 1980  
Doc. # 258581  
Found GLO monument in good condition  
SPRUCE N 74 W 13.20'