


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 144 R. R7 M. 5TH Coordinates: X _____ Y _____
NE 36 Corner common to sections 25, 36 AND 30, 31-144-26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees		
Species	<u>Rough Birch</u>	<u>Birch</u>	<u>Linn</u>	<u>Spruce</u>
Diameter	<u>14"</u>	<u>12"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>S72E</u>	<u>S41W</u>	<u>N72E</u>	<u>N10W</u>
Distance	<u>6LKS</u>	<u>20LKS</u>	<u>18LKS</u>	<u>14LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1937 By GLO
Location filed SEC. OF STATE
Monument Found SE, SW & NW B.T remains set
concrete mon. 2' long 6" dia. w/ brass cap T144N

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

	Bearing	Trees, Reference Objects		
Species	<u>Balsam</u>	<u>Balsam</u>	<u>Birch</u>	<u>Cedar</u>
Diameter	<u>8"</u>	<u>7"</u>	<u>7"</u>	<u>20"</u>
Bearing	<u>N77 1/4 E</u>	<u>S68 3/4 E</u>	<u>S21 1/2 W</u>	<u>N60 1/2 W</u>
Distance	<u>61 LKS</u>	<u>37 LKS</u>	<u>51 LKS</u>	<u>89 LKS</u>

Bearing Trees, Reference Objects

Bearing	Trees, Reference Objects	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILG STEAM - 1970 - FILED IN 1980
Doc. # 258679
Found GLO monument in good condition
17" Cedar N88W 33.70';
5" Green Ash N22E 25.70';
8" Black Ash S18E 61.40'