


T. 144 R. 27 M. 5TH Coordinates: X _____ Y _____
MC #19 Corner common to sections 35, 36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter NO trees
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1937 By GLO
Location filed Sec. of State
Monument Set 1x36" l.b. willow sap South 0.19ch.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

WC
T144N/R27W
S35/S36
MC
1937

Bearing Trees, Reference Objects

Species N. Pine J. Pine
Diameter 24" 12"
Bearing N35 1/4 E N14 W
Distance 265 LKS 247 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEAN - 1970 - FILED IN 1980
Doc. # 258580
found GLO monument in good condition
8" W. OAK N55W 100.50'
5" Palm of Gilead N14E 5.00'

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____