


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. X 25

CASS COUNTY LAND CORNER RECORD

T. 144 R. 27 M. 5TH Coordinates: X _____ Y _____
E' 14 36 Corner common to sections 36 and 31-144-26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Bearing Trees

Species	<u>Birch</u>	<u>Bl. Pine</u>	_____
Diameter	<u>12"</u>	<u>24"</u>	_____
Bearing	<u>N 58 W</u>	<u>S 12 E</u>	_____
Distance	<u>21 LKS</u>	<u>27 LKS</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By GLO
Location filed Sec. of State
Monument Set 1x36" i.p. w/ brass cap from orig B.T.
28" Dead Bl Pine S 12 E 27 LKS
114
536/531
1937

Bearing Trees, Reference Objects

Species	<u>J. Pine</u>	<u>N. Pine</u>	_____
Diameter	<u>7"</u>	<u>16"</u>	_____
Bearing	<u>N 81 1/4 E</u>	<u>S 82 1/2 W</u>	_____
Distance	<u>79 LKS</u>	<u>66 LKS</u>	_____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1970 - FILED IN 1980
Doc. # 258610
Found GLO monument in good condition.
8" Red Pine N 1 E 62.50'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____