


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. A 25

CASS COUNTY LAND CORNER RECORD

T. 144 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 1 Corner common to sections 1 And 6-144-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost C.C.

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Birch Birch _____
Diameter 5" 6" _____
Bearing S20W S9E _____
Distance 60 LKS 74 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1937 By GLO
Location filed Sec. of State
Monument Set 2' long 7" dia concrete mon. 20" inground
w/ brass cap proportionate dist. T145N R27W

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees Reference Objects
Species N. Pine N. Pine CC
Diameter 14" 9" T144W
Bearing S16"4E S76"2W _____
Distance 377 LKS 198 LKS _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____