


Index No. G 25

CASS COUNTY LAND CORNER RECORD

T. 144 R. 20 M. 5th Coordinates: X _____ Y _____
E 114 12 Corner common to sections 12 AND 7-144-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Tam</u>	<u>Tam</u>	
<u>3"</u>	<u>3"</u>	
<u>N20E</u>	<u>57W</u>	
<u>12 LKS</u>	<u>9 LKS</u>	

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By GLO
Location filed Sec. of State
Monument Set 1x36" I.P. w/brass cap 1/4
5/2/57
1937

Evidence of Subsequent Corner Restoration

Year of search 1994 By Terry Freeman
Found 1" x 3/16" G.L.O. brass cap monument. Lowered monument & tie to proportional position.
12-28-94 placed 2" iron pipe w/brass cap over 8" steel sign post. 3-16-95 Cert. Filed by Terry Freeman, RLS 21367, Doc. #365386

Bearing Trees, Reference Objects

Species Nikne
Diameter 10"
Bearing N143/4E
Distance 217 LKS

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Norway Pine</u>	<u>Norway Pine</u>	<u>1937 G.L.O. monument</u>
<u>19"</u>	<u>29"</u>	<u>22"</u>
<u>N53E</u>	<u>N16E</u>	<u>S16°53'20"E</u>
<u>271.54</u>	<u>264.70</u>	<u>12.39</u>
		<u>263.50</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____